

(see FIG. 2c)





FIG. 2b



Suggested Replacement
hole in 17 = 0.56"
hole in 3 = 0.37"

FIG. 2c

FIG. 2b

